COFCH

00862.002746.1



PATENT

of Correction

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: Peter B. Kim
MITSUYA SATO)	
	:	Group Art Unit: 2851
Appln. No.: 09/940,461)	•
	:	Patent No.: 6,771,353 B2
Filed: August 29, 2001)	
•	:	Issued: August 3, 2004
For: EXPOSURE APPARATUS AND)	
METHOD, DEVICE	:	
MANUFACTURING METHOD,)	October 8, 2004
AND DISCHARGE LAMP	:	
		- Certificate
Commissioner for Patents		
P.O. Box 1450		OCT 1 5 2004

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Attention: CERTIFICATE OF CORRECTIONS BRANCH

Sir:

Alexandria, VA 22313-1450

Patentees request that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency

10/12/2004 CNGUYEN 00000107 6771353

01 FC:1811

100.00 OP

should be charged and any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

Attorney for Patentees Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2200

SEW/klm

DC_MAIN 178541v1

00862.002746.1 <u>PATENT</u>

IN THE UNITED STATES P	ATENT AND TRADEMARK OFFICE
Livre Patent of:)
& TRAD	: Examiner: Peter B. Kim
MITSUYA SATO)
	: Group Art Unit: 2851
Appln. No.: 09/940,461)
	: Patent No.: 6,771,353 B2
Filed: August 29, 2001)
	: Issued: August 3, 2004
For: EXPOSURE APPARATUS AND)
METHOD, DEVICE	:

Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

MANUFACTURING METHOD,

AND DISCHARGE LAMP

Attention: CERTIFICATE OF CORRECTIONS BRANCH

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

October 8, 2004

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency

should be charged and any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

Attorney for Patentees

Steven E. Warner Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2200

SEW/klm

DC_MAIN 178541v1

Staple Here Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,771,353 B2

DATED : August 3, 2004

INVENTOR(S): MITSUYA SATO

Page 1 of 2

COLUMN 1:

Line 20, "i line-light" should read --i line light--.

COLUMN 5:

Line 11, "light," should read --light.--. Line 24, "point." should read --unit.--

COLUMN 7:

Line 16, "fly eye's" should read --fly's eye--. Line 24, "of" should read -- of the--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,771,353 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)



PRINTER'S TRIM LINE

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,771,353

: August 3, 2004 **DATED**

INVENTOR(S): MITSUYA SATO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 2, "ship" should read --chip--.

COLUMN 10:

Line 19, "apparatuses" should read --apparatus--. Line 24, "senor," should read --sensor,--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,771,353 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)



PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,771,353 B2

DATED : August 3, 2004

INVENTOR(S): MITSUYA SATO

Page 1 of 2

COLUMN 1:

Line 20, "i line-light" should read --i line light--.

COLUMN 5:

Line 11, "light," should read --light.--. Line 24, "point." should read --unit.--

COLUMN 7:

Line 16, "fly eye's" should read --fly's eye--. Line 24, "of" should read -- of the--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,771,353 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)



PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,771,353

: August 3, 2004 DATED

INVENTOR(S): MITSUYA SATO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 2, "ship" should read --chip--.

COLUMN 10:

Line 19, "apparatuses" should read --apparatus--. Line 24, "senor," should read --sensor,--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,771,353 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)